

Overland Mountain Bike Association							
Trail Agent Program							
USFS Canyon Lakes District Trails List							
Trail Area name	Trail #	Trail Name	OHV or Non-motorized	Bicycle status	Trail Mileage	Maintenance Issues Notes	Misc. Notes/ Planned Projects
Deadman/Pearl Beaver	956	Killpecker	OHV motorcycle only	Allowed	4.4	significant drainage issues and erosion in multiple areas, no brushing or obstructions issues	Trail Closed: in burn area
Deadman/Pearl Beaver	953	North Lone Pine (Bald Mtn)	No-Mo	Allowed	4.73	Top of trail may be impacted by Cameron Peak Fire. Ongoing tree clearing; Improve check dams; narrow trail width	Trail Closed: in burn area
Deadman/Pearl Beaver	950	Pearl Creek	No-Mo	Allowed	2.47	significant atv use evident, several drainage, brushing or obstructions issues	
Deadman/Pearl Beaver	970	Swamp Creek Cutoff	OHV motorcycle only	Allowed	3.07	Impacted by Cameron Peak fire significant drainage issues and erosion in multiple areas	Trail Closed: in burn area between #517 (Elkhorn-Baldy) and the Swamp Creek Road network (#171, A-L)
Donner Pass	926	Donner Pass	OHV motorcycle only	Allowed	8.9	Impacted by Cameron Peak fire	Trail Reopened July 1, 2021
Donner Pass	926-1	Donner Pass Cutoff	No-Mo	Allowed	0.57	Impacted by Cameron Peak fire	Trail Reopened July 1, 2021
Donner Pass	927	Indian	No-Mo	Allowed	0.86	Impacted by Cameron Peak fire	Trail Reopened July 1, 2021
Donner Pass	934	Lookout Mountain	OHV motorcycle only	Allowed	5.8	Impacted by Cameron Peak fire	Trail Reopened July 1, 2021
Donner Pass	934-1	Lookout Mountain Summit	No-Mo	Allowed	0.57	Impacted by Cameron Peak fire	Trail Reopened July 1, 2021
Donner Pass	997	Miller Fork	No-Mo	Allowed	2.04	Impacted by Cameron Peak fire	Trail Reopened July 1, 2021
Glen Haven	931	Crosier Mountain	No-Mo	Allowed	7.7	significant drainage issues and erosion in multiple areas	
Glen Haven	931-2	Crosier Mountain H-G	No-Mo	Allowed	0.47	significant drainage issues and erosion in multiple areas	
Glen Haven	931-1	Crosier Mountain Summit	No-Mo	Allowed	0.25		
Glen Haven	981	Crosier Rainbow	No-Mo	Allowed	2	significant drainage issues and erosion in multiple areas	
Homestead Meadows	971-2	Engert Homestead	No-Mo	Allowed	0.94	Needs trail check ride summer 2021	
Homestead Meadows	949-2	Griffith Homestead	No-Mo	Allowed	0.15	Needs trail check ride summer 2021	
Homestead Meadows	971-3	Hill Homestead	No-Mo	Allowed	0.67	Needs trail check ride summer 2021	
Homestead Meadows	971	Homestead Meadows	No-Mo	Allowed	0.67	Needs trail check ride summer 2021	
Homestead Meadows	971	Homestead Meadows (Pierson Park)	No-Mo	Allowed	2.77	Needs trail check ride summer 2021	

Trail Area name	Trail #	Trail Name	OHV or Non-motorized	Bicycle status	Trail Mileage	Maintenance Issues Notes	Misc. Notes/ Planned Projects
Homestead Meadows	971-1	Irvin Homestead	No-Mo	Allowed	0.82	Needs trail check ride summer 2021	
Homestead Meadows	971-10	Irvin Loop	No-Mo	Allowed	0.23	Needs trail check ride summer 2021	
Homestead Meadows	971-11	Irvin Sawmill	No-Mo	Allowed	0.1	Needs trail check ride summer 2021	
Homestead Meadows	949	Lion Gulch	No-Mo	Allowed	3.4	significant drainage issues and erosion in multiple areas	
Homestead Meadows	949-1	Lion's Paw	No-Mo	Allowed	0.15	Needs trail check ride summer 2021	
Hwy 34	969	Round Mountain (Summit Adventure Trail)	No-Mo	Allowed	4.64	Needs trail check ride summer 2021	
Hwy 34	969-1	Round Mountain Nature (Foothills)	No-Mo	Allowed			
Jacks Gulch	983	Jacks Gulch CG Loop Trail	No-Mo	Allowed	1.31	Impacted by Cameron Peak fire	Trail Closed: in burn area
Lady Moon	991-4	Box Hollow	No-Mo	Seasonally July 1 - Oct. 31	1.3	Needs trail check ride summer 2021	
Lady Moon	985-2	Disappointment Falls	No-Mo	Seasonally July 1 - Oct. 31	0.64	Needs trail check ride summer 2021	
Lady Moon	994	Elkhorn Creek	No-Mo	Seasonally July 1 - Oct. 31	2.85	Needs trail check ride summer 2021	WRV project planned for 2021/2022 to rebuild/build trails in this area.
Lady Moon	991	Granite Ridge	No-Mo	Seasonally July 1 - Oct. 31	3.7	Needs trail check ride summer 2021	
Lady Moon	985	Lady Moon	No-Mo	Seasonally July 1 - Oct. 31	1.12	Needs trail check ride summer 2021	
Lady Moon	985-1	Lady Moon Meadow Loop	No-Mo	Seasonally July 1 - Oct. 31	1.4	Needs trail check ride summer 2021	
Lady Moon	991-1	Molly Lake	No-Mo	Seasonally July 1 - Oct. 31	0.14	Needs trail check ride summer 2021	
Lady Moon	991-3	Molly Moon	No-Mo	Seasonally July 1 - Oct. 31	3	Needs trail check ride summer 2021	991-2 on USFS site.
Mt. Margaret	976	Columbine	No-Mo	Allowed	1.04		
Mt. Margaret	976-1	Columbine North Loop	No-Mo	Allowed	0.6		
Mt. Margaret	976-1	Columbine Ridge	No-Mo	Allowed	0.9		976-12 on USFS site
Mt. Margaret	976-11	Columbine Ridge Loop	No-Mo	Allowed	0.4		976-21 on USFS site
Mt. Margaret	973-1	East Dowdy Lake	No-Mo	Allowed	2.3	Summer 2021 install bike trestle	
Mt. Margaret	973	Frog Pond	No-Mo	Allowed	3.2	some steep eroded sections	
Mt. Margaret	973-3	Frog Pond - East Loop	No-Mo	Allowed	0.4		
Mt. Margaret	973-2	Frog Pond - West Loop	No-Mo	Allowed	1.5		
Mt. Margaret	951	Lone Pine Creek	No-Mo	Seasonally in Cherokee Park SWA May 2 to August 31	4.86		seasonal recreation access to trailhead in Cherokee Park SWA May 2 to August 31

Trail Area name	Trail #	Trail Name	OHV or Non-motorized	Bicycle status	Trail Mileage	Maintenance Issues Notes	Misc. Notes/ Planned Projects
	979					some drainage, brushing or obstructions issues: Improve check dams; narrow trail width, address road erosion multiple spots, wet crossings, improve horse crossing. Summer 2021 install bike trestles (2)	Mount Margaret & Molly Lake - September 14th Possible bike bridge over South Lone Pine Creek? Installing bike trestles? Oct. 5 2019 WRV did one bike trestle post installation in gated fence on Frog Pond trail near West Dowdy Lake, no bike bridge, some cement block armoring of crossings on Frog Pond trail for vehicle access.
Mt. Margaret		Mount Margaret	No-Mo	Allowed		3.8	
Mt. Margaret	979-3	Mount Margaret Connector	No-Mo	Allowed	0.24		
Mt. Margaret	979-2	Mount Margaret Divide	No-Mo	Allowed	0.6		
Old Roach	965-1	Grace Creek	OHV	Allowed	3.54		
	954					Ford ramps eroded; upper end of gulch needs brush cut back; upper lollypop meadow multi-track eroded. Rollers after crossing 4 planned. Drainage repair. Major reroute of steep drainage section .25 miles past top of switchbacks on CW lollypop has been approved by USFS. Minor reroute of steep climb out of Gordon Creek valley planned.	11 log footbridges built Jan. to May 2021. 2 more planned. Rollers after crossing 4 planned. Drainage repair. Major reroute of steep drainage section .25 miles past top of switchbacks on CW lollypop has been approved by USFS. Minor reroute of steep climb out of Gordon Creek valley planned.
Poudre Canyon		Hewlett Gulch	No-Mo	Allowed		1.98	
	988					some drainage, brushing or obstructions issues: Improve check dams; narrow trail width, address road erosion multiple spots, wet crossings , steep eroded sections. Steep section at about mile 2 very eroded, goes straight up a 30% plus grade - needs major reroute and switchbacks added.	Planned improvements include brushing and corridor widening, waterbar and drainage issues improvements, log footbridges at some crossings, reroute of steep section and crossing 4.
Poudre Canyon		Lower Dadd Gulch	No-Mo	Allowed		3.54	
	952					Impacted by Cameron Peak fire from trailhead to trail mile 3.6. numerous steep sections, eroded trail sections	Trail Closed: in burn area. Note this is primarily a hiking trail, not rideable due to steepness, narrow tight switchbacks, rocky step ups. Major rebuild planned for 2021/2022
Poudre Canyon		Roaring Creek	No-Mo	Allowed		5.02	

Trail Area name	Trail #	Trail Name	OHV or Non-motorized	Bicycle status	Trail Mileage	Maintenance Issues Notes	Misc. Notes/ Planned Projects
Poudre Canyon	999	Young Gulch	No-Mo	Allowed	5.1	Impacted by High Park fire 2012 and flooding 2013. Major construction project, trail rerouted and rebuilt and reopened Oct. 2019	3 log footbridges completed fall 2020. Complete log footbridge on crossing 11.